| | 20 October 1041 | Service No. | Rank | . Name | Duty | |
|---|---------------------------------|--|----------------------------|--|--|--------------------------|
| Date | 20 October 1941 | pervice No. | Rank | . Name | Ducy | |
| Type of Aircraft | Hudson Mk. V | 1250969 | Sgt. | Hendy, A. | Pilot | Frederikshav |
| Serial No. | AM523 | 924911 | Sgt. | Symons, S.A. | 2nd Pilot/Na | v.Frederiksh |
| Squadron | No. 608 | 553835 | (Sgt.) Flt.Sgt. | Wright, W.P. | WOp. | Frederikshav |
| Code Letters | UL, OY or GT : F | 995408 | Sgt. | White, W. | AG | Frederikshav |
| Base | | | | | | |
| Mission | Rover Patrol | | | | is the state of th | |
| Target | Shipping or opportunity targets | | | | | |
| Special Remarks: Left 1155 hrs. 20th Oct. | | | | | | |
| With no shipping seen by patrol of 'F', 'M' and 'T' of No. 608 Sqn., the patrol | | Diary of | Commander-in | -Chief of the German N | aval Force | s in Denmark |
| made for Danish coastal regions, to attack base at Thisted where He 59s were | | 3 Hudsons areas bet | between 155 ween a line | 9 and 1615 hrs. peneta 6 miles SW of Hansthol | ating Jutl m and 9 mi | and coastal les SE of |
| seen on water and machine-gunned. 'F' was seen to go in low between two | | Hanstholm | -Thisted. | * | | |
| buildings at Thisted seaplane station and drop bombs near slipway. It banked | | | | | | |
| away but shortly afterwards an aircraft was seen on ground burning which was | | Hudson Mk. V, AM523 on 20 October 1941 at 1615 hrs. shot down | | | | |
| assumed to be 'F'. One of the other Hudsons bombed a factory. | | at Faartoft by Luftwaffe flak. Aircraft crashed in farm house. | | | | |
| | | No survivors. | | | | |
| | | | | | jh | 3/69 · |