

Date	27 January 1943	Service No.	Rank	Name	Duty	Cemetery
Type of Aircraft	Mosquito B Mk. IV	1315442	Sgt.	Dawson, James George	Pilot	Tveje-Merløse
Serial No.	DZ407	1254141	Sgt.	Cox, Ronald Harry	Nav.	Tveje-Merløse
Squadron	No. 105					
Code Letters	GB : R	<i>T/C 14.26 Markham</i>				
Base						
Mission	Bombing					
Target	Burmeister & Wain Diesel Engine Works					
Special Remarks:	Copenhagen					
Wg. Cdr. H.I. Edwards, V.C., D.F.C. led 9 Mosquito aircraft to target which was attacked at 1705 hrs. DZ365 leading damaged by flak. DK338 flown by Flt.Lt. J. Gordon aborted after being damaged when flying at 50 feet. DK336, <sup>48</sup> : P of No. 139 Sqdn. crashed nr. Shipdham on return, its crew being killed.		<i><del>Wg. Cdr. H.I. Edwards, V.C., D.F.C. led</del></i>				
		<i>DK336 G-B-P borrowed by 139 Sq.</i>				
		Aircraft collided with high-tension cables and treetops on return journey and crashed at 1715 hrs. at Tveje-Merløse 2 miles SW of Holbaek.				
DZ365 : V, DZ413 : K, DZ415 : A, DK302:D						
DK338 : C, DZ407 : R of No. 105 Sqdn. DZ379:H, DK336:P, DZ416:Q of No. 139 Sqdn.						

jh 3/69